



DATE: September 15th, 2022
TO: Members of the Board of Directors
FROM: John Gibson, Chief Plant Operator
SUBJECT: OPERATION REPORT, August 12th – September 15th 2022

Lift Station #1

After the completion of the fence extension by Coggins Fence & Supply, operators brought in matching red rock to fill in the low areas around the facility to create a clean finished site.



Storage Shed Removal

The storage shed has been completely removed by Heauser Hauling. Operators trimmed the redwood trees, hauled away brush and debris, scraped and leveled the roadways. Organized pvc inventory and lumber. Separated scrap metal and garbage for disposal.





Regulatory Compliance

- CIWQS: August “No Spill Report” was completed.
- Completed sewer lateral inspections for 3855 Ross Rd, 8880 Donald St, and 3027 Arroyo Ct. Issued a sewer lateral certificate of compliance for each of the properties.

Operations, Process Control, and Preventative Maintenance

- Emptied the rags and grit from the Hippo Hopper collection system at the headworks for disposal.

- Continued irrigation on GCSD’s irrigation fields as a means of pond level management, monitoring for runoff and breaks in the system.

- Cleaned site around the plant, removing garbage and debris. Disposed of two 55 gal. drums of waste polymer at the Laguna treatment. Recycled old tires and building materials left behind from the plant upgrade.

- Repaired faulty connection on the 75hp effluent pump.

- Continued daily rag removal and weekly shoveling of the grit chambers at the headworks. Draining rags and grit in perforated buckets and disposing in the hippo hopper.

- Drain and cleaned the turbidity meters, sensors, and housing weekly.

- Performed weed abatement around plant roadways.

- Emailed signed tank agreement to Univar Solutions. Pending delivery and installation of the liquid chlorine storage container.

- Completed AC and tow hitch repairs on the Dodge #15 utility vehicle.

- Ford Ranger has a head gasket failure and a leaking radiator. Currently in the shop for radiator replacement and repair.

- The Capstone Micro Turbine faulted due to a bad internal fuel compressor. Cal Micro Turbine is onsite and in process of replacing the compressor.

